

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2016

Submitted Date:

12/01/2016

Document Number:

685501523**FIELD INSPECTION FORM**Loc ID 319810 Inspector Name: MONTOYA, JOHN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Condill, J.B.		jbcrog@aol.com	
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	<a href="#">All Inspections</a>
Espinosa, Bill		billespinosa30@yahoo.com	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201440	WELL	PR	12/30/1984	GW	001-06843	STATE 36-16	PR

**General Comment:**

SURE WOULD BE NICE IF I COULD GO TO YOUR LOCATIONS WITHOUT BANDAIDS ON STUFF THAT NEEDS TO BE TAKEN CARE OF, AND THE WORK WAS COMPLETED RIGHT

Location			
<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	OK		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	WEEDS NEED CONTROLLED		
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "		Date: 12/11/2016
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	Separator	<= 1 bbl	
Comment:	SOILED DIRTR AND VIC CLAMPS NEED TO BE REPLACED THEY LEAK OIL THIS IS THE SECOND TIME NO MORE YOU NEED TO REPAIR THESE CLAMPS		
Corrective Action:	"Comply with Rule 603.f using the Rule 603.f guidance document for further details. "		Date: 12/11/2016
In Containment: Yes			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	1" PIPE FENCE SE CORNER N39.91403 W-104.37864		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Deadman # & Marked	# 4		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:



**Inspected Facilities**

Facility ID: 201440 Type: WELL API Number: 001-06843 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
INTERMITTER CONTROLLER ON WELLHEAD DOCUMENT# 671106396, DATED 2/22/16 BERMS REPAIRED, VIC CLAMPS STILL LEAKING IN SEPERATOR, WEEDS NEEDS CONTROLLED ACTION REQUIRED, YOU HAVE 10 DAYS, GOOD LUCK, NEXT TIME IT GOES TO ENFORCEMENT, YOU NEED TO DO THE REPAIRS RIGHT NO BANDAIDS	montoyaj	12/01/2016

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685501523	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017363">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017363</a>
685501525	WELL SIGN	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017021">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017021</a>
685501527	CONTROL WEEDS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017022">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017022</a>
685501529	CONTROL WEEDS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017023">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017023</a>
685501530	CONTROL WEEDS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017024">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017024</a>
685501531	LEAKING FITTINGS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017025">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017025</a>
685501532	LEAKING FITTINGS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017026">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017026</a>
685501533	OIL LEAKING ON DIRT INSIDE SEPERATOR	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017027">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017027</a>
685501534	MORE LEAKING FITTINGS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017028">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4017028</a>