

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/09/2016

Submitted Date:

12/13/2016

Document Number:

680200054**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 322394      KELLERBY, SHAUN      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 64310Name of Operator: NORTHSTAR GAS COMPANY INCAddress: PO BOX 440789City: HOUSTON      State: TX      Zip: 77244**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Zachary, Casey		ccaseyzachary@aol.com	<a href="#">Ops Manager</a>

**General Comment:**

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type			
Comment:			
Corrective Action:		Date:	01/13/2017

Emergency Contact Number:

Comment: Sign not posted or information inaccurate

Corrective Action: Install sign to comply with Rule 210.b.

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
Condensate	WELLHEAD	>= 5 bbls		
Comment:	Gas and condensate venting from well head. Operator installed bull plugs by the end of the day on 12/9			
Corrective Action:	Contact Cogcc Enviromental staff to report spill.			Date: 12/15/2016

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	Well head was venting at the time of inspection. Bull plug was installed by the end of the day on 12/9. Cogcc engineering staff was notified by BLM staff on 12/8 of venting.		
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date: