



Photo#1: There is no evidence of the AL Well on this Active Location.

December 14, 2016

Inspection Photos: Encana AL Cedar Springs Ranch API# 045-09883



Photo#2: There is no evidence of the AL Well on this Active Location with one PR Well

Inspection Photos: Encana AL Cedar Springs Ranch API# 045-09883

December 14, 2016