



Photo#1: There is no evidence of the AL Wells on this Active Location.



Photo#2: There is no evidence of the AL Wells on this Active Location with Two PR Wells

Inspection Photos: Laramie ALs Loc#335520

January 18, 2017