

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2017

Submitted Date:

02/14/2017

Document Number:

674103938**FIELD INSPECTION FORM**
 Loc ID 440920 Inspector Name: Rickard, Jeff On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
General, All inspections	(970) 332-3520	cogccinspection@pdce.com	<a href="#">All PDC inspection</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440898	WELL	DG	05/04/2016	LO	123-41168	Jacobucci 32K-323	WK

**General Comment:**

**Inspected Facilities**

Facility ID: 440898 Type: WELL API Number: 123-41168 Status: DG Insp. Status: WK

**Complaint**

Comment: Complaint #:200441037

Field Inspector Assigned: Jeff Rickard

Location #: 440920

Inspection Document #: 674103938

Nature of complaint: Noise

If Sound GPS Coordinates of Survey Location: 40.01476,-104.91651

Inspection Observations:

OGCC inspector returned to location today and wind conditions were suitable to run a sound survey. The OGCC inspector was able to run a 30 minute survey before the wind speed rose above 30mph. The survey was run on CR4 by the complainants driveway at the GPS coordinates shown above. The survey resulted in a LeqC of 59.6 db

18ADoc#200441095

Corrective Action:

Date:

**Completion**

Operation:

Date Flowback:

Contractor:

Comment: Awaiting flowback

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

Complaint #:200441037

rickardj

02/14/2017

Field Inspector Assigned: Jeff Rickard

Location #: 440920

Inspection Document #: 674103938

Nature of complaint: Noise

If Sound GPS Coordinates of Survey Location: 40.01476,-104.91651

Inspection Observations:

OGCC inspector returned to location today and wind conditions were suitable to run a sound survey. The OGCC inspector was able to run a 30 minute survey before the wind speed rose above 30mph. The survey was run on CR4 by the complainants driveway at the GPS coordinates shown above. The survey resulted in a LeqC of 59.6 db

18ADoc#200441095

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674103939	Photo of sound survey location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075509">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075509</a>
674103940	Sound survey.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075510">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4075510</a>