

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2017

Submitted Date:

03/08/2017

Document Number:

684903231**FIELD INSPECTION FORM**Loc ID 440284 Inspector Name: Pesicka, Conor On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10373Name of Operator: NGL WATER SOLUTIONS DJ LLCAddress: 3773 CHERRY CRK NORTH DR #1000City: DENVER State: CO Zip: 80209**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Patterson, Joshua	970.356.5560	Joshua.Patterson@nglep.com	VP of Operations

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440282	WELL	IJ	04/16/2015	DSPW	123-40770	NGL C9B	SI

General Comment:

Inspected FacilitiesFacility ID: 440282 Type: WELL API Number: 123-40770 Status: IJ Insp. Status: SI**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: LYNS

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 02/25/2015

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: Verification of Repairs Tbg psi: 0 Csg psi: 0 BH psi: 0Insp. Status: Pass

Comment: init: 2275 psi
5 min: 2275 psi
10 min: 2275 psi
15 min: 2275 psi
g/l: -0- psi

Corrective Action: _____ Date: _____

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI for recent repairs- clean injection zone, replace tbg

Corrective Action: _____ Date: _____

BradenHeadComment: Bradenhead plumbed to surface.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401228424	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4093440
684903232	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4093431