

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2017

Submitted Date:

03/24/2017

Document Number:

678200647**FIELD INSPECTION FORM**Loc ID 448384 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 49888Name of Operator: LARIO OIL & GAS COMPANYAddress: PO BOX 29City: DENVER State: CO Zip: 80201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Eastwood, Blair	(720) 457-6567	blair@lario.net	<a href="#">Production Technician</a>
Anderson, Christina		chris@lario.net	<a href="#">All Inspections</a>
Axelson, John		john.axelson@state.co.us	

**General Comment:**[Environmental inspection related to the drilling pit. See pit sampling Corrective Action \(Date\).](#)

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Drilling PitLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: 

Corrective Action

Prior to backfilling the drilling pit (after the pit contents have dried sufficiently), collect a minimum of two discrete soil samples for laboratory analysis of BTEX and TPH to ensure compliance with Table 910-1 allowable levels. Provide the analytical results along with a sample location drawing to the NE EPS (rob.young@state.co.us). Contact NE EPS with if the pit contents have not dried sufficiently by the Corrective Action Date.

Date: 04/14/2017c**Fencing:**Fencing Type: Fencing Condition: Comment: 

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment: 

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: 

Corrective Action

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678200648	View west across drilling pit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108678">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108678</a>
678200649	View north across the middle of the drilling pit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108679">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108679</a>
678200650	View north across the west edge of the drilling pit	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108680">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108680</a>