

Taichert 32-02 #1 – API 05-067-06641

COGCC – Compliance follow up of the Erosional control

Tasks Completed:

Built BMP's on the NW and E sides of location

Cleaned out ditches and fixed berms on all sides of the location

Smoothed out two track road that had riling

Cleaned up sediment that was compiling up on the location

Reseeded areas that needed some stabilization







