

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2017

Submitted Date:

04/25/2017

Document Number:

673504195**FIELD INSPECTION FORM**

Loc ID 307573 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
113377	PIT	AC	09/23/1999		-	RATTLESNAKE 14-34	AC
217850	WELL	PR	11/23/1998	GW	071-06629	C BROWN 14-34	RI

General Comment:[This is an Interim Reclamation and Stormwater Management Inspection.](#)

Location**Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type			
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [The southwest cut-slope of the location is not stabilized and sediment is accumulating around the equipment. There is a plastic bucket partially buried which appears to be used as secondary containment for a valve at vert. separator. The bucket is full of water and is not an adequate BMP. See Attached Photos](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 05/26/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: _____ Pit ID: 113377 Lat: 37.210790 Long: -104.665630

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____

Date: c

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: [The water level in the pit is nearing the 2 ft freeboard marker.](#)

Corrective Action _____

Date: _____

Monitoring:	Monitoring Type	Comment
	Chain	
	Chain	

COGCC Comments

Comment	User	Date
A 502 b. variance request was submitted related to closure and reclamation of the C. Brown 14-34 Offsite pit. The variance request form 4 was returned to draft for document revisions.	CostaR	04/25/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673504196	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4131720