



STATE OF  
COLORADO

Complaints - DNR, DNR\_COGCC <dnr\_cogcc.complaints@state.co.us>

## [#919] COGCC Complaint Received

1 message

**COGCC Complaints** <dave.kulmann@state.co.us>

Mon, May 15, 2017 at 8:55 AM

Reply-To: usnewfie@comcast.net

To: dave.kulmann@state.co.us

COGCC Received your Complaint

Column	Value
<b>Date of Complaint</b>	5/15/2017
<b>Your Name</b>	Brian Hogan
<b>Your Address</b>	1385 Northview Dr
<b>Your City and State</b>	Erie
<b>Your Zip Code</b>	80516
<b>Your Phone (Used only to follow up)</b>	<a href="tel:3038850036">3038850036</a>
<b>Location of Concern</b>	A sign on the entrance states: KPK. Billings #21-7 and NENW Sec7-TIN-R68W. It appears to be owned by Liberty Oil Field Services. There is another sign that states "Wooley 11-7 battery" It is located north of County Road 10 1/2 and a 1/4 mile east of County Line road in Weld County (Town of Erie).
<b>Do you know who the oil and gas company is? If so, please specify and if you contacted them already please indicate that and who you talked with.</b>	KPK
<b>Email Address</b>	<a href="mailto:usnewfie@comcast.net">usnewfie@comcast.net</a>
<b>Would you like to answer additional optional questions related to the issues you are experiencing? If so, click the appropriate issue from the below list. If not, click "NO". Then click "Continue".</b>	Noise
<b>Is it noise you hear, noise you feel, or both?</b>	Both
<b>Do you know the source of the noise?</b>	Hydraulic Fracturing Operation
<b>Is it continuous or intermittent?</b>	Continuous
<b>When did the noise start?</b>	4/25/2017
<b>Is it happening right now?</b>	Yes,
<b>Is it happening right now?</b>	Yes,
<b>Detailed description of the issue or issues.</b>	,Very loud drilling and engine noise. It is clear that the sound abatement wall around the drilling site does not cover the entire operation.
<b>Does the noise typically occur the same time of the day? If so, please specify the time (i.e. early morning, early evening, etc.)</b>	All day

<b>Type of Complaint (Click all that apply)</b>	Noise
<b>Detailed description of the issue or issues.</b>	,Very loud drilling and engine noise. It is clear that the sound abatement wall around the drilling site does not cover the entire operation.
<b>Well or facility name and number (If known).</b>	Wooley 11-7
<b>In addition to noise, would you like to answer additional OPTIONAL questions related to another issue you are experiencing? If so, click the appropriate issue from the below list. If not, click "NO". Then click "Continue".</b>	NO -- I JUST WANT TO SUBMIT NOW
<b>What is your preferred method for the COGCC to communicate with you throughout the investigation? (Select all that apply)</b>	Phone
<b>Waste Management Additional Comments (The more details the better)</b>	''
<b>Waste Management Additional Comments (The more details the better)</b>	''
<b>Waste Management Additional Comments (The more details the better)</b>	''