

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2017

Submitted Date:

05/19/2017

Document Number:

674005197**FIELD INSPECTION FORM**Loc ID 434454 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS LLCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCInspections@extracti onog.com	All Inspectors
Gomez, Jason		jason.gomez@state.co.us	
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436336	WELL	PR	08/01/2015	OW	123-39053	Windsor LV A-14H	PR

General Comment:

Inspected Facilities

Facility ID: 436336 Type: WELL API Number: 123-39053 Status: PR Insp. Status: PR

Complaint

Comment: Complaint number: 200442581
Inspection number: 674005197

Wind speed exceed limit for performing sound survey.

Will attempt again as conditions permit.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Inspection conducted in response to complaint number: 200442581 Inspection number: 674005197 Current wind conditions exceed 5 mph limit for conducting noise survey. Will followup and conduct noise survey as conditions permit. Weather data included at attachment.	carlilec	05/19/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
674005198	Current wind data	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4152114