

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401298211

Date Received:

06/01/2017

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: K P KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Susana Lara-Mesa

303-825-4822

slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 684903665

Inspection Date: 05/02/2017

FIR Submit Date: 05/02/2017

FIR Status: _____

Inspected Operator Information:

Company Name: K P KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 317988

Location Name: MAHONEY-62N67W Number: 20NENE County: _____

Qtrqr: NENE Sec: 20 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.129740 Longitude: -104.908130

FACILITY - API Number: 05-123-00 Facility ID: 317988

Facility Name: MAHONEY-62N67W Number: 20NENE

Qtrqr: NENE Sec: 20 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.129740 Longitude: -104.908130

CORRECTIVE ACTIONS:

1 ☒ CA# 73758

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 12/09/2016

Response: CA COMPLETED

Date of Completion: 05/03/2017

Operator Comment: Removed stained soil at wellhead

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 73759

Corrective Action: Remove or remediate stained soil; Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 12/09/2016

Response: CA COMPLETED

Date of Completion: 05/03/2017

Operator
Comment: Removed stained soil at seperator house

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 73760

Corrective Action: Plumb bradenhead to surface

Date: 03/13/2017

Response: CA COMPLETED

Date of Completion: 05/03/2017

Operator
Comment: Bradenhead plumbed to surface

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed: _____

Title: VP of Engineering

Date: 6/1/2017 3:28:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401298211	FIR RESOLUTION SUBMITTED
401298221	Bradenhead
401298223	Seperator house

Total Attach: 3 Files