

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401304954

Date Received:

06/09/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: PO BOX 6501

City: ENGLEWOOD State: CO Zip: 80155

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Trujillo, Irwin

irwin_trujillo@xtoenergy.com

FITZGERALD EDIE

719-859-1394

edie_fitzgerald@xtoenergy.com

Harrison, Lyndon

lyndon_harrison@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 673504275

Inspection Date: 05/10/2017

FIR Submit Date: 05/12/2017

FIR Status: _____

Inspected Operator Information:

Company Name: XTO ENERGY INC

Company Number: 100264

Address: PO BOX 6501

City: ENGLEWOOD State: CO Zip: 80155

LOCATION - Location ID: 309581

Location Name: LOPEZ CANYON SWD-633S67W Number: 21NWSE County: LAS ANIMAS

Qtrqtr: NWSE Sec: 21 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.154726 Longitude: -104.889792

FACILITY - API Number: 05-071- -00 Facility ID: 300679

Facility Name: LOPEZ CANYON SWD Number: 1

Qtrqtr: NWSE Sec: 21 Twp: 33S Range: 67W Meridian: 6

Latitude: 37.154726 Longitude: -104.889792

CORRECTIVE ACTIONS:

1 CA# 75464

Corrective Action: Perform weed control at the location.

Date: 06/16/2017

Response: CA COMPLETED

Date of Completion: 05/18/2017

Operator
Comment:

The weeds were treated at this facility on 05/18/17. See attached photo's.

COGCC Decision: _____

COGCC
Representative:

2 CA# 75465

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 06/16/2017

Response: CA COMPLETED

Date of Completion: 06/08/2017

Operator
Comment:

Removed the sediment accumulation on the well pad. Established a bell hole at the toe of the rock run down to retain sediment. Installed a dirt berm on the terraced cut slope to re-direct run off away from the cut slope to an armored outlet. See attached photo's.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald

Signed: _____

Title: Senior Environmental Tech

Date: 6/9/2017 1:19:08 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
|-------------------------------|---------------------------|

| | |
|-----------|-------------------|
| 401304973 | follow up photo's |
|-----------|-------------------|

Total Attach: 1 Files