

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/06/2017

Submitted Date:

06/12/2017

Document Number:

666803221**FIELD INSPECTION FORM**

Loc ID 322296 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10043Name of Operator: MACKLEY* ARNOLD & DARLEENAddress: 4031 COUNTY RD 320City: RIFLE State: CO Zip: 81650**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Murray, Richard	970-623-9782	G.Richard.Murray@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210181	WELL	DM	02/24/1961	GW	045-05076	ED T. BERNKLAU 1	DM

General Comment:

Inspected FacilitiesFacility ID: 210181 Type: WELL API Number: 045-05076 Status: DM Insp. Status: DM**Workover**

Comment: June 6, 2017 Tuesday
PU 5-7/8 bit, XO, 4 4-1/16 drill collars, XO and XO to 2-3/8" tbg, RIH tag retainer and RU to Drill. Pumped drilling mud recovered from the well to circulate down tbg and taking returns to the cellar. Used a Vacuum truck to load fluid out of the cellar and return to the flat tank. Made about 1/2' in the 1st hr. Drilled to 4 pm without any discernable footage being made. Moved approximately 660 bbls from the cellar to the flat tank. POOH with tbg, Drill collars, Laid down bit which was still green. Sdf night.

Corrective Action:

Date: