

3/2/75

RECEIVED APR - 7 1975

The Application(s) for Permit to Drill (OGCC Form 2) enclosed herewith cannot be processed at this time for the reason(s) stated below:

- No bond
- Bond not signed
- No filing fee (\$75)
- Filing fee check not signed
- Application for Permit to Drill (OGCC Form 2) not signed
- Letter of waiver from owners of offsetting lease(s)
- Location not in accordance with Rule 318 or Spacing Order(s)
- Location not clearly reported
- Incomplete item(s) number(s) **.17 - which .80 ACRES** on Application to Drill (OGCC Form 2) **either S/2 & SW/4 or W/2 SW/4**
- Name of proposed objective horizon or geological formation
- Other

Please correct and resubmit.

4/7/75

OIL & GAS CONSERVATION COMMISSION

Gentlemen:

the Designated Area is the West 1/2 of the Southwest quarter. Notation thereof has been made on the enclosed Form 2 which is resubmitted herewith. Thank you.

75 270



Al Drake
CONTROLLER
MACHII-ROSS PETROLEUM

file