

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2017

Submitted Date:

06/15/2017

Document Number:

687900002**FIELD INSPECTION FORM**

Loc ID 322222 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16245Name of Operator: CHARLES ANTHONY FUNERAL HOMEAddress: 225 E MAINCity: FLORENCE State: CO Zip: 81226**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Harwood, Lloyd	719-458-1552/ 719-334-2445	harwoodfuneral@yahoo.com	Canyon City Office
Malin, Carol	719-458-1552	carol.harwoodfuneral@gmail.com	All Inspections
Adamczyk, Megan		megan.adamczyk@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210030	WELL	DM	05/12/1996	GW	043-06108	PRIDE OF WEST 1	DM

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	and separator surrounded by guard rail.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 210030	Type: WELL	API Number: 043-06108	Status: DM	Insp. Status: DM
Producing Well				
Comment:	PR - Domestic producer that heats Funeral Parlor and Retort Oven for crematorium.			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Paving	Pass	Paving	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At 9:00 am I called Harwood Funeral Services and talked to the office manager (Carol Malin). I told her that the COGCC had received a complaint on the "Pride of the West #1" well. The caller said the crematory was smoking. Carol Malin said they cremate at night and earlier in the week they had cremated a man in excess of 500 lbs. The more fat a person has, the more smoke they produce. I told Carol and Lloyd Harwood that I was driving up to Florence today, but if I got there after business hours, I would meet with them Monday (5/15/17) afternoon, because of a meeting Monday morning in Denver. I also called Brian Allen (Holt Funeral Home) and we set up a meeting for Tuesday (5/16/17) at 10:00 am.	duranj	06/15/2017