

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2017

Submitted Date:

06/16/2017

Document Number:

673504480**FIELD INSPECTION FORM**

Loc ID 320296	Inspector Name: COSTA, RYAN	On-Site Inspection <input type="checkbox"/>	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 5 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
2A Doc Num: _____			

Operator Information:

OGCC Operator Number: 10261

Name of Operator: BAYSWATER EXPLORATION AND PRODUCTION LLC

Address: 730 17TH ST STE 610

City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
Blyth, Tom	(303) 893-2503	tblyth@bayswater.us	
BARBULA, DON		dbarbula@bayswater.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203388	WELL	PA	12/20/2012	OW	001-08897	DOUBLE SHOT 11-15	RI

General Comment:

2017 Flowline NTO Inspection 1000' Buffer.
Well was plugged 12/20/2012.
This is also a Reclamation Inspection for PA Well API#001-08897.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: Cropland

Well plugged Pass

Pit mouse/rat holes, cellars backfilled Pass

Debris removed Fail

No disturbance /Location never built _____

Access Roads Regraded Fail

Contoured _____ Culverts removed _____

Gravel removed Fail

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured Fail

Compaction alleviation Fail Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage Fail

Weeds present Fail Subsidence Pass

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: There is gravel that remains along the access road and at the location. There is wooden timbers and metal rebar that remains at the location. The soils appear to be compacted and have not been regraded. There are noxious weeds growing along the access road and at the location. See Attached Photos.

Corrective Action:

Date **07/14/2017**

Comply with Rule 1004. Perform noxious weed control. Remove all debris. Regrade and decompact soils by cross ripping to a depth of 18 inches. Prepare the location for planting per landowner ag activity.

Overall Final Reclamation

Fail

Well Release on Active Location ☐Multi-Well Location ☐**COGCC Comments**

Comment	User	Date
There is a farming implement at the access road. Consult and coordinate with the landowner to remove implement to reclaim the area of the access road.	CostaR	06/16/2017
The surrounding field did not appear to have been planted with crop. The reclamation work should be performed before planting occurs.	CostaR	06/16/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401310714	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172496
673504481	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4172492