

PIONEER
NATURAL RESOURCES USA, INC.

PIONEER 34-27 TR

API 05-071-08548-0000

SW SE SECTION 27-32S-67W

WDID 1911598 / PERMIT # 73090-F

EMERGENCY No. 911 or 719-846-7898 (24 Hrs)

WDID 1911598 / Permit # 73090

07.05.2017 10:09



Produced water tank overflowed.



07.05.2017 10:10



07.05.2017 10:11



Down slope side of secondary containment berm. Berm was damaged during spill response.



Spill path. Spill flowed down hill a short distance.



View from spill path. Produced water tank in center of picture.