

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2017

Submitted Date:

07/15/2017

Document Number:

673715738**FIELD INSPECTION FORM**
 Loc ID 320625 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 41550Name of Operator: TYLER ROCKIES EXPLORATION LTDAddress: P O BOX 119City: TYLER State: TX Zip: 75710-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Strawn, Mark	(930) 595-4886	texcomo@sbcglobal.net	
Behrens, Vic	(303) 810-6382	behrens@netecin.net	
Hall, Dan	(303) 966-9610	dan@energyop.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204006	WELL	IJ	01/01/2017	ERIW	005-06089	PEORIA J-SAND UNIT 27	SI

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-395-7239

Corrective Action: _____ Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 204006 Type: WELL API Number: 005-06089 Status: IJ Insp. Status: SI**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 06/06/2014

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

BradenHead

Comment: BH pressure was 15 psi and took 15 seconds to blowdown after one month. Well will be rechecked for pressure on 9/8/2017 (2 months) and a gas sample for gas composition and the extended stable isotope analysis if needed. A small amount of gas venting was visible from BH valve after blowdown.

5/10/2016 59 psi, 1 min to blowdown. 6/13/2017 25 psi, 15 sec to blowdown.

Jan 2017 last production data reported to COGCC database.

Corrective Action: **Report production via Form 7 as required by Rule 206.** Date: 08/18/2017

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401343067	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4198634
673715743	TREX Peoria J-Sand Unit 27 UIC BH	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4198628