

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/28/2017

Submitted Date:

07/28/2017

Document Number:

675103767**FIELD INSPECTION FORM**Loc ID 375675 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 72085Name of Operator: PETRO-CANADA RESOURCES (USA) INCAddress: 717 17TH STREET #2900City: DENVER State: CO Zip: 80031**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		mkorenblat@suncor.com	
		deborah.thomas@hro.com	
		petrobinson@suncor.com	
		sherri.robbs@nblenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201260	WELL	PA	06/09/2000	OW	001-06663	CHAMPLIN 113 AMOCO A 1-13	RI

General Comment:

This is a follow-up final reclamation and stormwater inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control **Fail** _____

Non cropland: Revegetated 80% **Fail** _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

<p>Inspection Doc. #682501480 required operator to reclaim areas of the well location, and portions within the fenced remediation area that remain unvegetated. Inspector was unable to find any evidence that reclamation activities have been conducted. See attached photo document, and photo document from Inspection Doc. #682500940 for additional details. Per previous conversations and email correspondence w/ Noble/Petro-Canada. And extension of 5/31/2017 had been provided to perform the required reclamation. Refer to doc. #2225689. CA and CA date remains in place.</p>	<p>Date 05/31/2017</p>
<p>Corrective Action: Location does not meet reclamation requirements; insufficient vegetative cover. Area of the well location remains unvegetated and will require additional seeding. Portions within the fenced remediation area also remain unvegetated and may require additional remediation. Remediate soils (if needed) until soil meets COGCC 910-1 standards. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of predisturbance or reference area levels. Use a seed mixture requested by the landowner. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Reclamation activities shall be complete by 5/31/2017</p>	
<p>Overall Final Reclamation Fail Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/></p>	

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Inspection Doc. #682501480 required operator to install site specific stormwater and sediment control BMPs to prevent further degradation to the downslope area of the well location. No BMPs have been installed or maintained. Per previous conversations w/ Noble/Petro-Canada. And extension of 5/31/2017 had been provided to perform the required reclamation. Refer to doc. #2225689. CA and CA date remains in place.

Corrective Action: Properly select and install site specific stormwater and sediment control BMPs to prevent further degradation. Maintain BMPs until final reclamation has passed.

Date: 05/31/2017

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675103768	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4210089