

Inspected Facilities

Facility ID: 442545 Type: LAND API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat)	(Long)
Drill Cuttings	Land Application	Adequate		
Comment	It appears all E&P drilling waste has been incorporated. No stockpiles or standing liquids were observed. Post application soil sample results indicate that the soil onsite complies with the Table 910-1 Concentration Levels or are within background concentrations. Therefore, it appears that no further action is necessary at this time and the COGCC approves the land application site closure request. However, should future conditions at the site indicate contaminant concentrations in soils exceeding COGCC standards or if ground water is found to be impacted, then further investigation and/or remediation activities may be required.			
Corrective Action				Date:

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700584	South end application area looking northwest	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4212992
679700585	South end application area looking north	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4212993