

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/10/2017

Submitted Date:

08/07/2017

Document Number:

679100119**FIELD INSPECTION FORM**Loc ID 306936 Inspector Name: KUBECZKO, DAVE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Naomi Azulai		naomi.azulai@bp.com	

General Comment:Date of Inspection: 5-10-17Type of Inspection: Construction, Containment, StormwaterLocation Name: Merry Federal GU-M34N6W 10NWNE Pad; Merry Federal 2 WellLocation ID #: 306936Form 2A# NAAPI #: 05-067-09076

Temporary stormwater and containment BMPs for this well pad and access road from previous construction events are in-place and these stormwater controls indicate no offsite migration of fluids or sediment; cut and fill slopes of the original well pad have been partially re-vegetated; no evidence of leaks or spills at wellhead; tank has secondary containment - no evidence of leaks or spills; signage for wellhead is adequate; straw and straw waddles placed beyond fill slopes for surface soil erosion control; location is within a designated setback location; no evidence of fugitive dust or odors reaching nearby residence during operations.