

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/27/2017

Submitted Date:

08/07/2017

Document Number:

679100112**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
311916 _____ KUBECZKO, DAVE _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10464
 Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
 Address: 1801 BROADWAY #1000
 City: DENVER State: CO Zip: 80202

Findings:

1 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Nolan Redmon		nredmond@catamountep.com	
Dave Kubeczko		dave.kubeczko@state.co.us	

General Comment:

Date of Inspection: 7-27-17
 Type of Inspection: Wildlife Consultation, Containment, Stormwater
 Location Name: IGW N33N8W 6SESW Pad; IGW 124 and IGW 125 wells
 Location ID #: 311916
 Form 2A# 401317831
 API #: 05-067-09298 and 05-067-09349

Construction stormwater BMPs for well pad (diversion trenches, straw wattles, and other spill stormwater control equipment) and access road (borrow ditch for sediment control) are in-place and these stormwater controls indicate no evidence of offsite migration of fluids or sediment; existing stormwater controls indicate no offsite migration of fluids or sediment to nearby ditch and wetlands to the north of the well pad; however, based on the recent onsite and inspection (7-27-17) conducted by COGCC, additional stormwater controls will be required for the existing well pad area and the tank containment area of this oil and gas location; some cut and fill slopes have been partially re-vegetated; no evidence of leaks or spills at wellhead; tank has secondary containment - no evidence of leaks or spills; signage for tank and wellhead are adequate; CPW indicated that deer timing should be adhered to if possible; however, this location has a surface owner waiver of all CPW recommended wildlife BMPs.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401367394	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4218821