



L.G. EVERIST, INC.
ROCK SOLID SINCE 1876

7321 E. 88TH AVENUE, SUITE 200
HENDERSON, COLORADO 80640
PHONE 303-287-9606 • FAX 303-289-1348

September 5, 2017

Murray Herring
TOP Operating
3609 S. Wadsworth Blvd.
Lakewood, CO 80235

Dear Murray,

As you know, L.G. Everist, Inc. is the owner of the surface of lands where some of TOP Operating Co.'s wells are located. Those wells include the wells TOP recently plugged, the Watkins 2, Schneiders 1, 3 and 4, Ewing 2, Hitchings 1 and others. TOP has indicated its desire to remove production equipment from the above lands including pumping units, separators, storage tanks, etc., as well as remove the access road and complete reclamation activities.

Everist is continuing to conduct mining activities in the immediate vicinity of some of these former operating areas. Due to safety concerns and potential operational conflicts, Everist kindly requests that TOP continue to leave the area as it is until further notice.

If you have any questions, please contact me.

Sincerely,

Matthew Noteboom, GM-Mountain Division

L.G. Everist, Inc.