

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 1: Wellhead sign.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 2: Disconnected wellhead and riser.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 3: Unused risers on the N side of location W of meter run house.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 4: Unused risers on the E side of meter run house.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 5: Unused riser and abandoned flowline at meter run.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 6: Unused riser at wellhead.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 7: Unused riser S side of separator.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 8: Unmarked deadman painted orange by inspector.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 9: Unused risers along S side W of deadman.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 10: Unused risers marked with painted rocks and deadman in left of frame.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 11: Thistle going to seed along S perimeter.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 12: Thistle going to seed out from tank battery.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 13: Unused riser inside tank berms.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 14: Impacted soil and gravel under valve. One of several that need to be cleaned up.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 15: Soil pile just out of NW corner of location.

- Santa Fe Canyon Fed 42 - 7
- 05-033-06055



Photo 16: Graveled area with partial berms in NW corner of location.