

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/25/2017

Submitted Date:

09/12/2017

Document Number:

675103918

FIELD INSPECTION FORM

Loc ID 312291 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 1165 DELAWARE STREET #200
City: DENVER State: CO Zip: 80204

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		tcrumley@comcast.net	
		rob.young@state.co.us	
		steve@westernoperating.com	
		dale@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221078	WELL	IJ	01/01/2017	DSPW	075-09204	Propst 1	RI

General Comment:

[This is an interim reclamation and stormwater inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

Inspected Facilities

Facility ID: 221078 Type: WELL API Number: 075-09204 Status: IJ Insp. Status: RI

Producing Well

Comment: [PR, IR and SW inspection.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Substantial and ongoing erosion concerns exist to the east, south and west of the produced water pit have degraded the adjacent lands and vegetation.

Corrective Action See "COGCC Comments" for corrective action.

Date 11/15/2017

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: Substantial and ongoing erosion concerns exist to the south and west of the produced water pit. Until more permanent stabilization controls have been implemented and reclamation activities conducted, temporary stabilization controls will need to be implemented and maintained to prevent further degradation.						Date: 10/12/2017
Corrective Action: Properly select, install and maintain stormwater and sediment control BMPs in accordance to 1002.f and good engineering practices.						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						
Type: <u>Produced Water</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:		
Reference Point: _____	Other: _____	Length: _____	Width: _____			
Lining:						
Liner Type:		Liner Condition:				
Comment:						Date: <u>c</u>
Corrective Action						
Fencing:						
Fencing Type:		Fencing Condition:				
Comment:						Date:
Corrective Action						
Netting:						
Netting Type:		Netting Condition:				
Comment:						Date:
Corrective Action						
Anchor Trench Present:		Oil Accumulation:		2+ feet Freeboard:		
Comment: Substantial erosion from the east, south and west produced water pit berms has occurred, likely a result from produced water discharge.						Date: 10/12/2017
Corrective Action: Collect and test soil sample(s) from the bare area(s) below the pit location, and sample from a reference area, for comparative laboratory analysis of pH, EC and SAR. Report the results attached to a form 4 compared to the Table 910-1, and provide a map outlining sample locations to COGCC Reclamation specialist Aaron Trujillo by corrective action date of 10/12/2017.						
If sample from impacted area(s) is(are) greater than Table 910-1 standards, operator will submit a form 27 to EPS Rob Young (rob.young@state.co.us).						

COGCC Comments

Comment	User	Date
<p>CORRECTIVE ACTION:</p> <p>If soil sampling and analysis indicates areas do not meet 910-1 standards, perform remediation and maintain stabilization BMPs until standards are met, at which point revegetation activities shall be conducted. If areas meet 910-1 standards, reclaim the disturbed areas in accordance to COGCC 1000 series reclamation rules and standards; Re-grade disturbed areas and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until reclamation has passed. Remediation and/or revegetation activities shall be conducted no later than 11/15/2017</p>	trujilloam	09/12/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401400752	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4249079
675103919	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4249071