



# COLORADO OIL & GAS CONSERVATION COMMISSION

## NORTHEAST REGION FIELD INSPECTION REPORT

☒ NOTICE OF UNSATISFACTORY INSPECT  
☐ NOTICE OF SATISFACTORY INSPECTIO.



02528749

337 Cambridge

h, CO 80723 970-842-4465

Date: 11-14-01 Facility ID: \_\_\_\_\_ Operator: Intermountain  
Location: SENW 29-9N-56W Lease Name: S. Teal #2  
API Number: 05-123-14584 Inspector: **ED BINKLEY** Cell: 970-380-2683

INSP ☒ INSP STATION ☒ RECLAM ☐ PASS ☐ INTER ☐ PASS/FAIL ☐ P ☒ VIOLATION ☐ Y ☒ NOV ☐ Y ☒  
UIC VIOL TYPE: ☐ UA ☐ MI ☐ OP ☐ PA ☐ OT TBG/PKR LK ☐ CSG LK ☐ ALL UIC VIOLATIONS REQUIRE NDAYS

Well ID Signs Comments: \_\_\_\_\_ Fences **Y** **N** Comments: \_\_\_\_\_  
(Rule 210) Y **N** (Rule 603.b.(7), 1002.a)

Production Pits (Rule 902, 903, 904) EARTHEN PITS ONLY  
SENSITIVE AREA ☐ YES ☒ NO  
Produced Water Pits Total # 1 Oil Accumulation? ☐ YES ☒ NO  
Comments: Box 400'  
Skimming/Settling Pits Total # 1 Covered # 1 Uncovered # \_\_\_\_\_  
Comments: \_\_\_\_\_  
Special Purpose Pits Total # \_\_\_\_\_ Lined # \_\_\_\_\_ Unlined # \_\_\_\_\_  
Comments: \_\_\_\_\_

Tank Battery Equipment (Rule 604) Tank, HHT, pump ☐  
BURIED OR PARTIALLY BURIED VESSELS: #STEEL \_\_\_\_\_ #FIBERGLASS \_\_\_\_\_ #CONCRETE \_\_\_\_\_ #OTHER \_\_\_\_\_

Fire Walls/Berms/Dikes [Rule 604.a.(4)] ☒

General Housekeeping (Rule 603.g) ok well plugged ☐

Spills (Oil/Water) (Rule 906) ☐

UIC Routine Inspection FILL OUT FORM 21 WHEN WITNESSING MIT  
Inj. Pressure \_\_\_\_\_ Psig COMMENTS  
T-C Ann. Pressure \_\_\_\_\_ Psig  
RECEIVED  
NOV 15 2001

Drilling Well/Workover (Rule 317) Yetter w/s plugged per permit - 4000' casing recovery ☐  
(Andy)

Surface Rehabilitation (Rule 1003, 1004) (grassland) ☐

Miscellaneous LIBP @ 5700 @ 2 1/2 x Calt 50 1/2 x cant @ 185', 10 1/2 x top plug - ☐

CORRECTIVE ACTION REQUIRED: Remove equipment, submit form 27 for pit closure plan and restore site to approval.  
Date Corrective Action Required By: 11-14-02 Date Remedied: \_\_\_\_\_

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.