

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401448494

Date Received:

11/02/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Tesla Dougherty

970-304-5245

tesla.dougherty@nblenergy.com

Abby Bazin

720-587-2356

abby.bazin@nblenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 675103767

Inspection Date: 07/28/2017

FIR Submit Date: 07/28/2017

FIR Status: _____

Inspected Operator Information:

Company Name: PETRO-CANADA RESOURCES (USA) INC

Company Number: 72085

Address: 717 17TH STREET #2900

City: DENVER State: CO Zip: 80031

LOCATION - Location ID: 375675

Location Name: CHAMPLIN 113 AMOCO A-63S59W Number: 23NESE County: _____

Qtrqtr: NESE Sec: 23 Twp: 3S Range: 59W Meridian: 6

Latitude: 39.773266 Longitude: -103.946641

FACILITY - API Number: 05-001-00 Facility ID: 375675

Facility Name: CHAMPLIN 113 AMOCO A-63S59W Number: 23NESE

Qtrqtr: NESE Sec: 23 Twp: 3S Range: 59W Meridian: 6

Latitude: 39.773266 Longitude: -103.946641

CORRECTIVE ACTIONS:

1 CA# 88345

Corrective Action:

Date: 05/31/2017

Location does not meet reclamation requirements; insufficient vegetative cover. Area of the well location remains unvegetated and will require additional seeding. Portions within the fenced remediation area also remain unvegetated and may require additional remediation. Remediate soils (if needed) until soil meets COGCC 910-1 standards. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of predisturbance or reference area levels. Use a seed mixture requested by the landowner. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Reclamation activities shall be complete by 5/31/2017

Response: CA COMPLETED

Date of Completion: 11/02/2017

Operator Comment: Noble has removed and replaced impacted soil, replaced topsoil, seeded and crimped, and fenced off areas to allow vegetation to regrow.

COGCC Decision:

COGCC Representative:

2 CA# 88346

Corrective Action: Properly select and install site specific stormwater and sediment control BMPs to prevent further degradation. Maintain BMPs until final reclamation has passed.

Date: 05/31/2017

Response: CA COMPLETED

Date of Completion: 11/02/2017

Operator Comment: Stormwater BMPs including wattles were installed to prevent erosion.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tesla Dougherty

Signed:

Title: EHS Specialist

Date: 11/2/2017 1:35:00 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files