

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/30/2017

Submitted Date:

12/01/2017

Document Number:

679700681**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
ALLISON, RICK 2A Doc Num: _____

Operator Information:OGCC Operator Number: 4680Name of Operator: DCP MIDSTREAM LPAddress: 370 17TH STREET - SUITE 2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hayes, Branden	970-373-8905	bshayes@dcpmidstream.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453259	SPILL OR RELEASE	AC	11/30/2017		-	CR 62 Pipeline Release	EI

General Comment:

Environmental**Spill/Remediation:**

Comment: COGCC Environmental Staff responded spill reported by DCP near Weld county Road 62 & 47. According to an onsite contractor an excavation crew constructing a new driveway related to the county road widening of WCR 47 struck a 3" DCP pipeline causing a gas and condensate release. The condensate misted a residence and the gravel and road base in the rear of the house. The residents were temporarily evacuated during the incident. Impacted material around the residence had been removed and further excavation around the pipeline was pending utility locates.

Corrective Action: Form 19 Supplemental Report is due 12/8/2017. DCP is to report cleanup of residence and affected soil using future Form 19 Supplemental Reports.

Date: 12/08/2017

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____