

Robin Frazier Gas Unit A 1 inspection corrective action work 12-11-17



Emergency numbers have been added to the old sign temporarily as a new sign was ordered and has yet to arrive. A new sign will be installed to replace this old sign as soon as the manufacturing of it has been completed and it has been delivered.



Unused equipment has been removed and location has been back dragged and smoothed out



Unused equipment has been removed and location has been back dragged and smoothed out



Unused equipment has been removed and location has been back dragged and smoothed out



Unused equipment has been removed and location has been back dragged and smoothed.