



00248009

CGCC FORM 1
Rev. 9/89

STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY



SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

☒ OIL WELL ☐ GAS WELL ☐ COALBED METHANE ☐ INJECTION WELL ☐ OTHER

NAME OF OPERATOR

Denver East Machinery Co

ADDRESS OF OPERATOR

15507 E. 18th Ave

CITY

STATE

ZIP CODE

Aurora

CO

80011

LOCATION OF WELL (Report location exactly and in accordance with any State requirements. See the back of this form.)
At surface

2030' FN

As proposed 3rd 1995

2030' FW

COUNTY

Logan

PERMIT NO.

89-519

APPROVAL

05 075 9202

WELL NAME

State Fuller

WELL NUMBER

2-22

FIELD OR WILDCAT

Logan

OIL OR GAS SEC. FA AND WELDIAN

SENV 22-8N-54W

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A NOTICE OF INTENTION TO:

- ☒ PLUG AND ABANDON
☐ MULTIPLE COMPLETION
☐ COMMINGLE ZONES
☐ FRACTURE TREAT
☐ REPAIR WELL
☐ OTHER

13B SUBSEQUENT REPORT OF:

- ☒ FINAL PLUG AND ABANDONMENT
(SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOE LOG)
☐ ABANDONED LOCATION (WELL NEVER DRILLED)
SITE MUST BE RESTORED WITHIN 6 MONTHS
☐ REPAIRED WELL
☐ OTHER

*Use Form 3 - Well Completion or Abandonment Report and Log
(for subsequent report of Multiple Completion Completions
and Abandonment)

13C NOTIFICATION OF:

- ☐ SHUT-IN TEMPORARILY ABANDONED
(DATE _____)
(REQUIRED EVERY 6 MONTHS)
☐ PRODUCTION RESUMED
(DATE _____)
☐ LOCATION CHANGE (SUBMIT NEW PLAT)
☐ WELL NAME CHANGE
☐ OTHER

14 DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and cones pertinent)

15 DATE OF WORK 11-7-95

set CIBP at 5150 w/2 sks cement cut casing off
@ 4000' pulled 5 1/2 casing set plug at 800' - 700'
set plug 1/2 in 1/2 out of surface w/10 sks @ surface.
cut off casing 4' below ground level welded cap
on restore location

16. I hereby certify that the foregoing is true and correct.

SIGNED

TELEPHONE NO.

NAME (PRINT) Duane Freund

TITLE President

DATE

(This space for Federal or State office use)

APPROVED

TITLE

ENGR

DATE

6-19-96