

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2017

Submitted Date:

12/30/2017

Document Number:

671000813**FIELD INSPECTION FORM**Loc ID 418695 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 44390Name of Operator: JAVERNICK OILAddress: 3040 E MAINCity: CANON CITY State: CO Zip: 81212**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-------------------------------|----------------------|---------------------------------|
| Javernick, James | 719-275-3040/719-671-3787 | javernick1@gmail.com | All Inspections |
| Mehennett, Tom | (719) 275-3040/(505) 330-1328 | tbm3040@gmail.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 418701 | WELL | WO | 10/12/2012 | LO | 043-06196 | CHANDLER CREEK 24-32 | TA |

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Deadman # & Marked

0

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Wellhead

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 418701 Type: WELL API Number: 043-06196 Status: WO Insp. Status: TA**Cement**Cement ContractorContractor Name: Javernick OilContractor Phone: 719-275-3040Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment:

Plug was 2.5 ft long and had a diameter of 6.5 inches. The plug snagged and a smaller diameter plug will be put in tomorrow.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| On site at 4:50 pm. Cable was attached to wooden plug, but diameter of plug was too big. Will have to try again with different plug tomorrow. Off site at 5:30 pm (Dark). | duranj | 12/20/2017 |