

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401506891

Date Received:

01/08/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611
Name of Operator: LONGS PEAK RESOURCES LLC
Address: 2323 S SHEPHERD SUITE 1150
City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
David Clarkson	214-534-9569	dclarkson@vrtxep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403163
Inspection Date: 01/03/2018 FIR Submit Date: 01/04/2018 FIR Status:

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC Company Number: 10611
Address: 2323 S SHEPHERD SUITE 1150
City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 438066

Location Name: RAILAY Number: 28-3-1CH County:
Qtrqtr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6
Latitude: 40.985310 Longitude: -104.783590

FACILITY - API Number: 05-123-00 Facility ID: 438066

Facility Name: RAILAY Number: 28-3-1CH
Qtrqtr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6
Latitude: 40.985310 Longitude: -104.783590

CORRECTIVE ACTIONS:

1 CA# 113733

Corrective Action: Comply with Rule 603.f . Date: 02/01/2018

Response: CA COMPLETED Date of Completion: 01/09/2018

Operator Comment: Unused Equipment will be picked up and transported off location.

COGCC Decision:

COGCC
Representative:

2 CA# 113734

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.(2) Corrective actions from the previous inspection were not resolved; therefore, the corrective action date on this inspection remain the same from the previous inspection.

Date: 08/17/2017

Response: CA COMPLETED

Date of Completion: 01/09/2018

Operator Comment: It is anticipated that with the Interim Reclamation of the unused portions of the location that much of the stormwater controls will become unnecessary as the location size will be dramatically reduced. Any storm water controls which are still necessary will be installed or updated with necessary BMPs.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator will immediately begin interim reclamation on all areas of this location not reasonably needed for production operations from the currently existing well. Dirt work will begin as soon as One calls are cleared and re-seeding etc. will begin as soon as weather permits.
It is anticipated that this action will clear up all necessary corrective actions noted in this inspection report.
Operator will also keep other lines of communication open, (outside of this FIRR), with the COGCC as this process proceeds.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David Clarkson

Signed: _____

Title: COO

Date: 1/8/2018 6:14:47 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files