

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401498175
Date Received:
01/11/2018

FIR RESOLUTION FORM

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Susana Lara-Mesa	303-825-4822	slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 678300859
Inspection Date: 08/02/2017 FIR Submit Date: 08/14/2017 FIR Status: _____

Inspected Operator Information:

Company Name: K P KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 336643

Location Name: POPE Number: #3-17-21R County: _____
Qtrqtr: NENW Sec: 17 Twp: 4N Range: 66W Meridian: 6
Latitude: 40.318671 Longitude: -104.803413

FACILITY - API Number: 05-123-00 Facility ID: 451667

Facility Name: Lewis 2-20 battery Number: _____
Qtrqtr: NENW Sec: 17 Twp: 4N Range: 66W Meridian: 6
Latitude: 40.318671 Longitude: -104.803413

CORRECTIVE ACTIONS:

1 ☒ CA# 91906

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Date: 09/14/2017

Response: CA COMPLETED Date of Completion: 12/26/2017

Operator Comment: Hydrocarbon stained soils at crude AST at battery 451667 have removed. See attached picture.

COGCC Decision: Approved

followup inspection 6783001359

COGCC
Representative:

2 ☒ CA# 91907

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a.

Date: 09/25/2017

Response: CA COMPLETED

Date of Completion: 12/26/2017

Operator
Comment: Hydrocarbon stained soils at wellhead and riser near wellhead have removed. See attached picture.

COGCC Decision: Approved

COGCC
Representative: followup inspection 6783001359

3 ☒ CA# 91908

Corrective Action: Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details.
Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 08/24/2017

Response: CA COMPLETED

Date of Completion: 08/31/2017

Operator
Comment: Unused risers have tagged out. See attached pictures.

COGCC Decision: Approved

COGCC
Representative: followup inspection 6783001359

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed:

Title: VP of Engineering

Date: 1/11/2018 3:54:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401498175	FIR RESOLUTION SUBMITTED
401498190	Removed stained soils at crude AST PIC
401498193	Removed stained soils at wellhead PIC
401498195	Tagged out unused risers PIC1
401498198	Tagged out unused risers PIC2

Total Attach: 5 Files