

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401485434

Date Received:

12/13/2017

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Leonard, Mike

mike.leonard@state.co.us

Beebe, Sabre

970-375-7530

Sabre.Beebe@bp.com

Inspections, All

SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303916

Inspection Date: 10/24/2017

FIR Submit Date: 10/26/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 333122

Location Name: NORTHWEST CEDAR HILL Number: 23NWNW County: LA PLATA
32-10-N32N10W

Qtrqtr: NWN Sec: 23 Twp: 32N Range: 10W Meridian: N
W

Latitude: 37.007296 Longitude: -107.908229

FACILITY - API Number: 05-067- -00 Facility ID: 215982

Facility Name: Robin Frazier GU PLA 9 Number: 1

Qtrqtr: NWN Sec: 23 Twp: 32N Range: 10W Meridian: N
W

Latitude: 37.007296 Longitude: -107.908229

CORRECTIVE ACTIONS:

1 ☒ CA# 107635

Corrective Action: Remove unused equipment to comply with Rule 603.f.

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/08/2017

All unused equipment has been removed from location and the location back dragged to smooth out any ruts.

Operator
Comment: See attached photos

COGCC Decision: Approved

COGCC
Representative: Follow up inspection completed 12/20/2017 document number 685304104.

2 ☒ CA# 107636

Corrective Action: Install sign to comply with Rule 210.b.

Date: 11/26/2017

Response: CA COMPLETED

Date of Completion: 12/08/2017

Operator
Comment: The BP emergency number has been added to the location sign. I new sign is on order but has not been delivered as of 12/8/17. As soon as the new sign arrives it will be placed on location and the old sign will be removed. See attached photos

COGCC Decision: Approved

COGCC
Representative: Follow up inspection completed 12/20/2017 document number 685304104.

OPERATOR COMMENT AND SUBMITTAL

Comment: All Corrective actions have been completed see attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed:

Title: Construction Specialist

Date: 12/13/2017 3:55:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401485434	FIR RESOLUTION SUBMITTED
401485470	Inspection CA work completion photos

Total Attach: 2 Files