

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401499191  
Date Received:  
01/02/2018

## FIR RESOLUTION FORM

### CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) Fax: ( )  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com
Inspections, All		SanJuanCOGCC@bp.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 685303892  
Inspection Date: 10/18/2017 FIR Submit Date: 10/23/2017 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

### LOCATION - Location ID: 325309

Location Name: TYNER-LUNT(EPA)-M34N8W Number: 18NWSE County: LA PLATA  
Qtrqtr: NWSE Sec: 18 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.188694 Longitude: -107.756376

### FACILITY - API Number: 05-067- -00 Facility ID: 214537

Facility Name: TYNER-LUNT(EPA) Number: 1  
Qtrqtr: NWSE Sec: 18 Twp: 34N Range: 8W Meridian: M  
Latitude: 37.188694 Longitude: -107.756376

### CORRECTIVE ACTIONS:

1 ☒ CA# 106716

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4). Date: 11/23/2017

Response: CA COMPLETED Date of Completion: 12/15/2017

Operator Comment: Berming materials have been repaired and/or replaced around the tanks on this location please see attached photos of work completed 12/15/17

COGCC Decision: Approved pending re-inspection

COGCC Representative: Location will be scheduled for re-inspection.

2 ☒ CA# 106717

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 11/23/2017

Response: CA COMPLETED

Date of Completion: 12/15/2017

Operator Comment: Berming materials have been repaired and/or replaced around the tanks on this location please see attached photos of work completed 12/15/17

COGCC Decision: Approved pending re-inspection

COGCC Representative: Location will be scheduled for re-inspection.

3 ☒ CA# 106718

Corrective Action: Locate and mark all deadmen to comply with Rule 1003.a.

Date: 11/23/2017

Response: CA COMPLETED

Date of Completion: 12/15/2017

Operator Comment: Dead men have been marked that must remain. If no longer required they have been removed from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Location will be scheduled for re-inspection.

4 ☒ CA# 106719

Corrective Action: Locate and mark all anchors to comply with Rule 1003.a.

Date: 11/23/2017

Response: CA COMPLETED

Date of Completion: 12/15/2017

Operator Comment: Dead men have been marked that must remain. If no longer required they have been removed from location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Location will be scheduled for re-inspection.

5 ☒ CA# 106720

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f.

Date: 11/23/2017

Response: CA COMPLETED

Date of Completion: 12/15/2017

Operator Comment: Armouring has been installed in erosion channel see attached photos

COGCC Decision: Approved pending re-inspection

COGCC Representative: Location will be scheduled for re-inspection.

OPERATOR COMMENT AND SUBMITTAL

Comment: All CA's have been addressed on 12/15/17. In addition new signs have been installed at the entrance of location. See attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Construction Specialist

Date: 1/2/2018 7:54:29 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401499191	FIR RESOLUTION SUBMITTED
401499195	Work Completion photos

Total Attach: 2 Files