

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401465629  
Date Received:  
11/21/2017

FIR RESOLUTION FORM

CA Summary:  
4 of 4 CAs from the FIR responded to on this Form  
4 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10433  
Name of Operator: LARAMIE ENERGY LLC  
Address: 1401 SEVENTEENTH STREET #1400  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name Phone Email  
Lorne C Prescott 970 812 5311 lprescott@laramie-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680101555  
Inspection Date: 03/03/2017 FIR Submit Date: 03/05/2017 FIR Status:

Inspected Operator Information:

Company Name: LARAMIE ENERGY LLC Company Number: 10433  
Address: 1401 SEVENTEENTH STREET #1400  
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 449070

Location Name: Gunderson Number: 20-03 Pad County:  
Qtrqr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6  
Latitude: 39.266756 Longitude: -107.795281

FACILITY - API Number: 05-077-00 Facility ID: 449070

Facility Name: Gunderson Number: 20-03 Pad  
Qtrqr: NENW Sec: 20 Twp: 9S Range: 93W Meridian: 6  
Latitude: 39.266756 Longitude: -107.795281

CORRECTIVE ACTIONS:

1 CA# 66369  
Corrective Action: File From 42 NOTICE OF CONSTRUCTION ASAP. Staff will be communicating with Management & Enforcement re: Neglect /lack of Notification. Date: 03/06/2017

Response: CA COMPLETED Date of Completion: 03/06/2017

Operator Comment: Issues resolved

COGCC Decision: Approved

COGCC Representative:

2  CA# 66370

Corrective Action: Ditches, Appropriate BMPs need to be installed along Sides of Access Road.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 03/06/2017

Operator Comment: Corrective Actions Completed

COGCC Decision: Approved pending re-inspection

COGCC Representative:

3  CA# 66371

Corrective Action: Wattles, Appropriate BMPs need to be installed along Soil piled off & along Access Road on Fill side and all along North edge of Location where Topsoil has been piled close to LOD.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 03/06/2017

Operator Comment: Corrective Actions Completed

COGCC Decision: Approved pending re-inspection

COGCC Representative:

4  CA# 66372

Corrective Action: Roughening, Appropriate BMPs need to be installed along Soil piled off & along Access Road on Fill side and all along North edge of Location where Topsoil has been piled close to LOD.

Date: 03/09/2017

Response: CA COMPLETED

Date of Completion: 03/06/2017

Operator Comment: Corrective Actions Completed

COGCC Decision: Approved pending re-inspection

COGCC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lorne C Prescott

Signed: \_\_\_\_\_

Title: Reg & Enviro Compliance

Date: 11/21/2017 10:26:35 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
401465629	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files