

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401536888

Date Received:

02/06/2018

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611

Name of Operator: LONGS PEAK RESOURCES LLC

Address: 2323 S SHEPHERD SUITE 1150

City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

David Clarkson

214-534-9569

dclarkson@vrtxep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403163

Inspection Date: 01/03/2018

FIR Submit Date: 01/04/2018

FIR Status: _____

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC

Company Number: 10611

Address: 2323 S SHEPHERD SUITE 1150

City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 438066

Location Name: RAILAY Number: 28-3-1CH County: _____

Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.985310 Longitude: -104.783590

FACILITY - API Number: 05-123-00 Facility ID: 438066

Facility Name: RAILAY Number: 28-3-1CH

Qtrqr: NENW Sec: 28 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.985310 Longitude: -104.783590

CORRECTIVE ACTIONS:

1 ☒ CA# 113733

Corrective Action: Comply with Rule 603.f .

Date: 02/01/2018

Response: CA COMPLETED

Date of Completion: 01/30/2018

Operator
Comment:

Unused Equipment is picked up and transported off location.

COGCC Decision: Approved pending re-inspection

Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an

COGCC Representative: acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

2 ☒ CA# 113734

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.(2) Corrective actions from the previous inspection were not resolved; therefore, the corrective action date on this inspection remain the same from the previous inspection.

Date: 08/17/2017

Response: CA COMPLETED

Date of Completion: 01/25/2018

Operator Comment: Interim Reclamation is complete of the unused portions of the location for the referenced well. Many of the stormwater controls will be unnecessary as the location size is dramatically reduced.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC standards.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: David clarkson

Signed: _____

Title: COO

Date: 2/6/2018 10:27:41 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401536888	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files