


FORM 6 Rev 12/05	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <td style="width:25%;">DE</td> <td style="width:25%;">ET</td> <td style="width:25%;">OE</td> <td style="width:25%;">ES</td> </tr> </table> <p style="color: red; font-weight: bold;">Replug By Other Operator</p> <p>Document Number: 401524906</p> <p>Date Received: 01/31/2018</p>	DE	ET	OE	ES																
DE	ET	OE	ES																				
WELL ABANDONMENT REPORT																							
<p><small>This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.</small></p> <p><small>A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.</small></p>																							
<table style="width:100%;"> <tr> <td style="width:50%;">OGCC Operator Number: 10071</td> <td style="width:50%;">Contact Name: Matt Barber</td> </tr> <tr> <td>Name of Operator: BARRETT CORPORATION* BILL</td> <td>Phone: (303) 312-8188</td> </tr> <tr> <td>Address: 1099 18TH ST STE 2300</td> <td>Fax:</td> </tr> <tr> <td>City: DENVER State: CO Zip: 80202</td> <td>Email: mbarber@billbarrettcorp.com</td> </tr> </table>				OGCC Operator Number: 10071	Contact Name: Matt Barber	Name of Operator: BARRETT CORPORATION* BILL	Phone: (303) 312-8188	Address: 1099 18TH ST STE 2300	Fax:	City: DENVER State: CO Zip: 80202	Email: mbarber@billbarrettcorp.com												
OGCC Operator Number: 10071	Contact Name: Matt Barber																						
Name of Operator: BARRETT CORPORATION* BILL	Phone: (303) 312-8188																						
Address: 1099 18TH ST STE 2300	Fax:																						
City: DENVER State: CO Zip: 80202	Email: mbarber@billbarrettcorp.com																						
<p>For "Intent" 24 hour notice required, Name: Pesicka, Conor Tel: (970) 415-0789</p> <p>COGCC contact: Email: conor.pesicka@state.co.us</p>																							
<table style="width:100%;"> <tr> <td colspan="2">API Number 05-123-11062-00</td> <td colspan="2">Well Number: 1</td> </tr> <tr> <td colspan="2">Well Name: PACKARD</td> <td colspan="2"></td> </tr> <tr> <td>Location: QtrQtr: SWSE</td> <td>Section: 23</td> <td>Township: 5N</td> <td>Range: 61W Meridian: 6</td> </tr> <tr> <td colspan="2">County: WELD</td> <td colspan="2">Federal, Indian or State Lease Number:</td> </tr> <tr> <td colspan="2">Field Name: WILDCAT</td> <td colspan="2">Field Number: 99999</td> </tr> </table>				API Number 05-123-11062-00		Well Number: 1		Well Name: PACKARD				Location: QtrQtr: SWSE	Section: 23	Township: 5N	Range: 61W Meridian: 6	County: WELD		Federal, Indian or State Lease Number:		Field Name: WILDCAT		Field Number: 99999	
API Number 05-123-11062-00		Well Number: 1																					
Well Name: PACKARD																							
Location: QtrQtr: SWSE	Section: 23	Township: 5N	Range: 61W Meridian: 6																				
County: WELD		Federal, Indian or State Lease Number:																					
Field Name: WILDCAT		Field Number: 99999																					
<input checked="" type="checkbox"/> Notice of Intent to Abandon <input type="checkbox"/> Subsequent Report of Abandonment																							
<i>Only Complete the Following Background Information for Intent to Abandon</i>																							
Latitude: 40.381050 Longitude: -104.173580																							
GPS Data:																							
Date of Measurement: 04/06/2015 PDOP Reading: 2.0 GPS Instrument Operator's Name: Wyatt Hall																							
Reason for Abandonment: <input type="checkbox"/> Dry <input type="checkbox"/> Production Sub-economic <input type="checkbox"/> Mechanical Problems																							
<input checked="" type="checkbox"/> Other Re-enter to Replug																							
Casing to be pulled: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Estimated Depth:																							
Fish in Hole: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																							
Wellbore has Uncemented Casing leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No If yes, explain details below																							
Details:																							
Current and Previously Abandoned Zones																							
<table style="width:100%;"> <tr> <th>Formation</th> <th>Perf. Top</th> <th>Perf. Btm</th> <th>Abandoned Date</th> <th>Method of Isolation</th> <th>Plug Depth</th> </tr> <tr> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> <td> </td> </tr> </table>				Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth														
Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth																		
Total: 0 zone(s)																							
Casing History																							
Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status															
SURF	12+1/4	8+5/8	24	222	200	222	0	VISU															

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 140 sks cmt from 400 ft. to 0 ft. Plug Type: CASING Plug Tagged: ☒

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set 25 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. _____ inch casing Plugging Date: _____
of _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

BBC is submitting this NOI Form 6 for the purpose to re-enter and adequately re-plug prior to hydraulic stimulation as agreed in offset well mitigation, option 3. (DJ Basin Horizontal Offset Policy)

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Rachel Milne

Title: Regulatory Analyst Date: 1/31/2018 Email: rmilne@billbarrettcorp.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: JENKINS, STEVE Date: 2/15/2018

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 8/14/2018

COA Type

Description

	Provide 48 hour notice of plugging MIRU via electronic Form 42.
	Operator shall implement measures to control unnecessary and excessive venting, to protect the health and safety of the public, and to ensure that vapors and odors from well plugging operations do not constitute a nuisance or hazard to public welfare.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401524906	FORM 6 INTENT SUBMITTED
401524982	SURFACE AGRMT/SURETY
401530730	WELLBORE DIAGRAM
401530731	WELLBORE DIAGRAM
401530732	PROPOSED PLUGGING PROCEDURE
401530907	LOCATION PHOTO

Total Attach: 6 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	pass	02/15/2018
Public Room	Document verification complete 01/13/16	01/31/2018

Total: 2 comment(s)