

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401557531
Date Received:
02/28/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 6301 DEAUVILLE BLVD

City: MIDLAND State: TX Zip: 79706

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Michael Haub

970-697-8385

mhaub@chevron.com

Linda McMurry

lindamcmurry@chevron.com

Adriane Gifford

(713) 372-1022

AGifford@chevron.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 682502747

Inspection Date: 10/22/2017

FIR Submit Date: 10/26/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BRITISH AMERICAN OIL PROD CO

Company Number: 10558

Address: 6001 BOLLINGER CANYON RD

City: SAN RAMON State: CA Zip: 94583

LOCATION - Location ID: 389108

Location Name: CASEMENT 'A'-612N54W Number: 32SWSE County: _____

Qtrqtr: SWSE Sec: 32 Twp: 12N Range: 54W Meridian: 6

Latitude: 40.966094 Longitude: -103.427364

FACILITY - API Number: 05-075- -00 Facility ID: 389108

Facility Name: CASEMENT 'A'-612N54W Number: 32SWSE

Qtrqtr: SWSE Sec: 32 Twp: 12N Range: 54W Meridian: 6

Latitude: 40.966094 Longitude: -103.427364

CORRECTIVE ACTIONS:

1 CA# 107606

Corrective Action: Perform reclamation; remove pipe and various debris remaining at well and battery location and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed. Revegetation activities shall be complete no later than 3/31/2018.

Date: 03/31/2018

Response: CA COMPLETED

Date of Completion: 02/28/2018

Operator Comment: Chevron is working to move this case to an active operator number through a form 10 so that a form 4 can be submitted to extend the deadline outside of the winter months so that revegetation actives will have a much higher probability of success.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: It has taken some time for Chevron to determine if it is our legal responsibility to conduct the final reclamation on this well, as British American Oil Production Company is not a name that we conduct business under. Additionally, Chevron believes that achieving 80% natural ground cover by March 31st, 2018 is an unattainable request. Consequently, Chevron has now determined that it is probable that the reclamation is our responsibility and as such will agree to remediate the location, but due to the short timeframe are requesting an extension. This is being conducted in an FIR as operator number 10558 is not a number that we operate under. A form 10 will be submitted to request transfer of the well to an operating company that Chevron operates under in Colorado when the permitting specialist returns from vacation on Monday. After the form 10 is submitted, I will follow up with an official form 4 request for extension.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Haub

Signed: _____

Title: Colorado HES specialist

Date: 2/28/2018 7:14:48 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files