

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401461287
Date Received:
11/16/2017

FIR RESOLUTION FORM

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Beebe, Sabre		Sabre.Beebe@bp.com
.		SanJuanCOGCC@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680601965
Inspection Date: 08/24/2017 FIR Submit Date: 09/05/2017 FIR Status:

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY Company Number: 10000
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326055

Location Name: MORRISON FED GU G- N34N6W Number: 7NESE County: LA PLATA
Qtrqr: NESE Sec: 7 Twp: 34N Range: 6W Meridian: N
Latitude: 37.225639 Longitude: -107.564186

FACILITY - API Number: 05-067- -00 Facility ID: 215790

Facility Name: MORRISON FEDERAL B Number: 1
Qtrqr: NESE Sec: 7 Twp: 34N Range: 6W Meridian: N
Latitude: 37.225639 Longitude: -107.564186

CORRECTIVE ACTIONS:

1 ☒ CA# 97770

Corrective Action: Remove debris and materials from the well pad and interim reclamation areas, or provide a surface owner waiver letter that includes a map delineating the areas that the surface owner will use, and interim reclamation areas.

Date: 11/17/2017

Response: CA COMPLETED Date of Completion: 10/09/2017

Operator Comment: Landowner is stock piling concrete for irrigation ditch repairs in the spring. He has moved the blocks and concrete down grade from the well pad and will utilize debris in the ditch in the spring before irrigation water is turned on. All trash has been removed and fencing equipment belonging to the land owner has been removed

from location. See attached photos

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Land owner has moved debris and trash from the well pad. concrete and blocks have been move down grade of pad to stock pile of use in spring in his irrigation ditch for erosion control. 'CA for erosion has been delayed waiting on landowner to move trailers etc to allow for seeding equipment to work on erosion issues and cut slope. Erosion repairs are scheduled for November 27th.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 11/16/2017 9:58:06 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401461287	FIR RESOLUTION SUBMITTED
401461300	Landowner debris removal photos

Total Attach: 2 Files