

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	6' chain link		
Corrective Action:		Date:	

Venting:			
Yes/No	YES		
Comment:	Occuring when rolling hole to open top tank system advised operator of Policy on controls for VOC's		
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 414502 Type: WELL API Number: 001-09716 Status: SI Insp. Status: SI

Cement

Cement Contractor

Contractor Name: _____ Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 7830' Cement Volume (sx): 2

Good Return During Job: NO Cement Type: G-Neat

Comment: Observed WL unit RIH set CIBP @ 7830' WL RIH w/ DB set 2 sxs cement on CIBP

Corrective Action: Date: _____

Workover

Comment: TEC Well services performing P&A

Corrective Action: Date: _____