

FORM  
6Rev  
12/05

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Document Number:

401578169

Date Received:

## WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 17320

Contact Name: Julie Branting

Name of Operator: CITY &amp; COUNTY OF DENVER

Phone: (303) 506-4592

Address: 8500 PENA BLVD RM 9870

Fax:

City: DENVER State: CO Zip: 80249

Email: petropro@comcast.net

**For "Intent" 24 hour notice required,**

Name: Gomez, Jason

Tel: (970) 573-1277

**COGCC contact:**

Email: jason.gomez@state.co.us

API Number 05-031-06413-00

Well Name: CHAMPLIN 117 AMOCO

Well Number: A-4

Location: QtrQtr: SWNW Section: 7 Township: 2S Range: 65W Meridian: 6

County: DENVER

Federal, Indian or State Lease Number:

Field Name: THIRD CREEK

Field Number: 81800

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

### Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.894410

Longitude: -104.712720

GPS Data:

Date of Measurement: 09/15/2009

PDOP Reading: 1.6

GPS Instrument Operator's Name: Dennis Hamlin, Sr DIA

Reason for Abandonment:

☐ Dry☒ Production Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☐ Yes☐ No

Estimated Depth:

Fish in Hole: ☐ Yes☐ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☐ No

If yes, explain details below

Details:

### Current and Previously Abandoned Zones

| Formation | Perf. Top | Perf. Btm | Abandoned Date | Method of Isolation | Plug Depth |
|-----------|-----------|-----------|----------------|---------------------|------------|
| J SAND    | 8316      | 8352      | 07/27/2013     | BRIDGE PLUG         | 8192       |

Total: 1 zone(s)

### Casing History

| Casing Type | Size of Hole | Size of Casing | Weight Per Foot | Setting Depth | Sacks Cement | Cement Bot | Cement Top | Status |
|-------------|--------------|----------------|-----------------|---------------|--------------|------------|------------|--------|
| SURF        | 12+1/4       | 8+5/8          | 24              | 338           | 325          | 338        | 0          | VISU   |
| 1ST         | 8+5/8        | 5+1/2          | 15.5            | 8,430         | 500          | 8,430      | 300        | CBL    |

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 8192 with 2 sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

|   |                          |  |
|---|--------------------------|--|
| Set <u>10</u> sks cmt from <u>3550</u> ft. to <u>3450</u> ft. | Plug Type: <u>CASING</u> | Plug Tagged: <input type="checkbox"/>            |
| Set <u>10</u> sks cmt from <u>1700</u> ft. to <u>1600</u> ft. | Plug Type: <u>CASING</u> | Plug Tagged: <input checked="" type="checkbox"/> |
| Set <u>10</u> sks cmt from <u>770</u> ft. to <u>670</u> ft.   | Plug Type: <u>CASING</u> | Plug Tagged: <input type="checkbox"/>            |
| Set <u>10</u> sks cmt from <u>390</u> ft. to <u>290</u> ft.   | Plug Type: <u>CASING</u> | Plug Tagged: <input checked="" type="checkbox"/> |
| Set _____ sks cmt from _____ ft. to _____ ft.                 | Plug Type: _____         | Plug Tagged: <input type="checkbox"/>            |

Perforate and squeeze at 7300 ft. with 60 sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth

(Cast Iron Cement Retainer Depth)

Set \_\_\_\_\_ sacks half in. half out surface casing from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. Plug Tagged: ☐

Set 25 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_

\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_

Type of Cement and Additives Used: \_\_\_\_\_

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

pump 2 sks cement on CIBP at 8192'

Run in hole to 300', perf and circulate cement to surface and fill hole with cement

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Linda Pavlka

Title: Agent Date: \_\_\_\_\_ Email: lindapavelkalp@gmail.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: \_\_\_\_\_ Date: \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_ Expiration Date: \_\_\_\_\_

| COA Type | Description |
|----------|-------------|
|          |             |

### Attachment Check List

Att Doc Num

Name

|           |                      |
|-----------|----------------------|
| 401578171 | WELLBORE DIAGRAM     |
| 401578172 | WIRELINE JOB SUMMARY |

Total Attach: 2 Files

### General Comments

User Group

Comment

Comment Date

|  |  |                        |
|--|--|------------------------|
|  |  | Stamp Upon<br>Approval |
|--|--|------------------------|

Total: 0 comment(s)