

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401578180
Date Received:
03/18/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10658
Name of Operator: CAPTIVA ENERGY PARTNERS LLC
Address: PO BOX 281108
City: LAKEWOOD State: CO Zip: 80228
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>HAYWORTH, WILLIAM</u>		<u>bhayworth@captivaep.com</u>
<u>ONSAGER, PAUL</u>	<u>720-635-7813</u>	<u>ponsager@captivaep.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 682403364
Inspection Date: 03/02/2018 FIR Submit Date: 03/06/2018 FIR Status: _____

Inspected Operator Information:

Company Name: CAPTIVA ENERGY PARTNERS LLC Company Number: 10658
Address: PO BOX 281108
City: LAKEWOOD State: CO Zip: 80228

LOCATION - Location ID: 452112

Location Name: STILLROVEN FARM Number: PAD County: _____
Qtrqtr: NENE Sec: 5 Twp: 3N Range: 68W Meridian: 6
Latitude: 40.260750 Longitude: -105.018810

FACILITY - API Number: 05-123-00 Facility ID: 452112

Facility Name: STILLROVEN FARM Number: PAD
Qtrqtr: NENE Sec: 5 Twp: 3N Range: 68W Meridian: 6
Latitude: 40.260750 Longitude: -105.018810

CORRECTIVE ACTIONS:

1 CA# 114686

Corrective Action: E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Date: 03/06/2018

Response: CA COMPLETED Date of Completion: 03/05/2018

Operator Comment: Operator removed and disposed of E&P waste associated with drilling operations from the location.

COGCC Decision: _____

COGCC
Representative: _____

2 CA# 114687

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 04/03/2018

Response: CA COMPLETED

Date of Completion: 03/05/2018

Operator
Comment: Operator stabilized and compacted areas around sediment traps and compacted the BMP berm slope on the western edge of the location. Operator also installed a vehicle tracking pad at the entrance to the location following removal of rig mats that were used to protect buried pipelines.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Operator's contractor was on location during March 3-5, 2018 completing the corrective actions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Onsager

Signed: _____

Title: Partner

Date: 3/18/2018 5:15:39 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401578188	Photo taken from south of the drilled well looking north showing removal of E&P waste
401578189	Photo showing stabilization of sediment trap on SW corner of location
401578191	Photo looking south showing compaction of berm on west side of location
401578192	Photo looking north showing compaction of berm on west side of location
401578193	Photo showing stabilization of sediment trap on NW corner of location
401578194	Photo looking southeast showing vehicle tracking pad installed at entrance

Total Attach: 6 Files