



00266618

RADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- <u>075-09184</u>	LEASE NAME: <u>State 10-52</u>		
LOCATION: <u>SENW 7-10N-52</u>	OPERATOR: <u>Visual Optics</u>		
DATE: <u>1-23-96</u>	INSPECTOR: <u>Ed Binley</u>		
Insp. Type: <u>Pr</u>	Insp. Status: <u>Pr</u>	PA: Y N	Pass/Fail: P <u>Q</u> Viol.: Y N NOV: Y <u>N</u>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210)	<i>marginal, update</i>	
Pits (Reserve/Production) (Rule 902, 903, 904)	<i>602 pit</i>	
Fences (Rule 604.C.(3), 1003.A)	✓	
Tank Battery Equipment (Rule 604)	<i>2-400</i>	
Fire Walls/Berms/Dikes (Rule 604)	<i>berm needs improvement</i>	
General Housekeeping (Rule 603.G)	<i>— Keep oily dirt cleaned/cultivate</i>	
Spills (Oil/Water) (Rule 908)	<i>oily soil around treater (old)</i>	
Bradenhead (Rule 207)	3/18/96 THE WORK ON THIS WELL HAS BEEN COMPLETED	
Drilling Well/Workover (Rule 315)	VIS OP OIL BY: <i>John Elliff</i>	
Surface Rehabilitation (Rule 317)		
Miscellaneous		

CORRECTIVE ACTION REQUIRED: <i>Cultivate oily soil around treater, improve skim pit berm & cover.</i>	
Date Corrective Action Required By: <u>3-30-96</u>	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White - File Green - Operator Canary - Well Site