

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/13/2018

Submitted Date:

04/17/2018

Document Number:

685304601**FIELD INSPECTION FORM**Loc ID 313628 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10434Name of Operator: ATOM PETROLEUM LLCAddress: 3323 N MIDLAND DR #113City: MIDLAND State: TX Zip: 79707**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hughes, Jim		jimo.hughes@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Andrews, Dave		david.andrews@state.co.us	
Roy, Catherine		catherine.roy@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297954	WELL	SI	05/18/2016	OW	083-06653	DOERFER 1-5	SI

General Comment:[Inspection completed as part of plugging operations.](#)[See link at end of report for path to downloadable inspection pictures.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0		STEEL AST		,	
Comment: Tank drained and removed as part of plugging operation.						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance		
Comment:									
Corrective Action:								Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS		
CRUDE OIL		0		HEATED STEEL AST			,		
Comment:		Tank drained and removed as part of plugging operation.							
Corrective Action:								Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--	--	--

Inspected FacilitiesFacility ID: 297954 Type: WELL API Number: 083-06653 Status: SI Insp. Status: SI**Cement**Cement ContractorContractor Name: 4 Corners Well

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Wind advisory with gust in excess of 50 mph. Unsafe to move rig onto well.
 Relocated skid mounted pit and skid mounted pump from Doerfer 2 to Doerfer 1-5.
 Well prep completed as much as possible until rig is in place.
 Shut down for night.

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304626	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4442662