

Photo#1:

There is No Evidence of the PA Well on this Active Location.



April 16, 2018

Inspection Photos: Laramie PA BC 15-5 API#077-08627

Photo#2:

There is No Evidence of the PA Well on this Active Location with Two PR Wells.



April 16, 2018

Inspection Photos: Laramie PA BC 15-5 API#077-08627