


23-2N-58W



Tipps Drlg. Co., Inc.

D. S. T. No. 1

B. M. Young # 1

This recorder blanked off below the bottom packer and since pressure bled to only 1200 lbs., which is more than the shut-in pressure, the bottom packer held. Recorder No. 3-S-1

RECEIVED  
APR 17 1963

OIL & GAS  
CONSERVATION COMMISSION



00105332