

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401648134
Date Received:
05/21/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 792 BUCKHORN DR
City: RIFLE State: CO Zip: 81650
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Lujan, Carlos</u>		<u>carlos.lujan@state.co.us</u>
<u>Knudson, Dwayne</u>	<u>970-456-3335</u>	<u>dknudson@ursaresources.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 680102931
Inspection Date: 04/30/2018 FIR Submit Date: 05/03/2018 FIR Status: _____

Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC Company Number: 10447
Address: 1600 BROADWAY ST STE 2600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 436196

Location Name: Burckle Cuttings Staging Area Number: _____ County: _____
Qtrqtr: NWSE Sec: 16 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.523849 Longitude: -107.669499

FACILITY - API Number: 05-045-00 Facility ID: 436196

Facility Name: Burckle Cuttings Staging Area Number: _____
Qtrqtr: NWSE Sec: 16 Twp: 6S Range: 92W Meridian: 6
Latitude: 39.523849 Longitude: -107.669499

CORRECTIVE ACTIONS:

1 CA# 116222

Corrective Action: Remove totes and any stained soil or material. Contact COGCC EPS staff. Date: 06/04/2018

Response: CA COMPLETED Date of Completion: 05/10/2018

Operator Comment: Totes were removed and returned to tank cleaning company for recycling.

COGCC Decision: _____

Date: 5/21/2018 2:57:42 PM

Page 2 of 2