

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401652449

Date Received:

05/25/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed

0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 600 E EXCHANGE AVE

City: FORTH WORTH State: TX Zip: 76164

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Sephra Baca

Phone

8173785584

Email

sephra_baca@xtoenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680402769

Inspection Date: 05/11/2018

FIR Submit Date: 05/14/2018

FIR Status: _____

Inspected Operator Information:

Company Name: BOPCO LP

Company Number: 10172

Address: PO BOX 6501

City: ENGLEWOOD State: CO Zip: 80155

LOCATION - Location ID: 316375

Location Name: YELLOW CREEK FEDERAL-61S98W Number: 4SWSW County: RIO BLANCO

Qtrqtr: SWS Sec: 4 Twp: 1S Range: 98W Meridian: 6
W

Latitude: 39.987870 Longitude: -108.403660

FACILITY - API Number: 05-103- -00 Facility ID: 270716

Facility Name: YELLOW CREEK FEDERAL Number: 4-16 #1

Qtrqtr: SWS Sec: 4 Twp: 1S Range: 98W Meridian: 6
W

Latitude: 39.987870 Longitude: -108.403660

CORRECTIVE ACTIONS:

1 CA# 116340

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 05/25/2018

Response: CA COMPLETED

Date of Completion: 05/24/2018

5/21/2018 XTO Energy contacted Bob Keohler, COGCC UIC, Geology advisor
The bradenhead and production casing were bled down, the bradenhead plug was removed and properly
reinstalled, pressures were monitored. No significant pressure on the bradenhead or production casing was

Operator noted, leak was repaired.
Comment: 5/24/2018 XTO Energy contacted Craig Burger, Western Region Engineering Supervisor and discussed actions taken. Craig indicated satisfaction with actions taken but requested follow-up with inspector. Voice message left with inspector on 5/23/2018, (currently waiting for a response).

COGCC Decision: _____

COGCC
Representative:

--

OPERATOR COMMENT AND SUBMITTAL

Comment: 5/24/2018 XTO Energy contacted Craig Burger, Western Region Engineering Supervisor and discussed actions taken. Craig indicated satisfaction with actions taken but requested follow-up with inspector. Voice message left with inspector on 5/23/2018, (currently waiting for a response).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sephra Baca

Signed: _____

Title: Regulatory Analyst

Date: 5/25/2018 12:42:02 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files